

SES-000-87
14 September 1987

MEMORANDUM FOR: Distribution

THROUGH: Chief, Advanced Development Division, ESG

FROM: Laird Steinberg
System Engineering Support, GE

SUBJECT: Transition ERB Meeting Report

1. The Transition Engineering Review Board was held on 14 September 1987 at 1330. See Attachment A for a list of attendees. See Attachment B for the Agenda.

2. M. Tanigawa opened the meeting and reviewed the new critical DRs. See Attachment C for a description of DRs.

3. The new DRs were reviewed for comment. See Attachment C for a description of the new DRs.

4. The following DRs in process were reviewed for update. Time permitted only the Priority A DRs to be discussed. See Attachment D for the current status of all DRs, MRs, and RFCs.

5. The Action Items previously assigned at the T-ERB were reviewed. See Attachment E for the list of Action Items reviewed and generated during this meeting.

6. Open Discussion included 1 walk-on DR, number HU-DR-E-068-87. See Attachment C for a description of the new DR.

7. The next Transition ERB is scheduled for Thursday, 17 September at 1330.

Laird Steinberg

Attachments

SES-000-87

SUBJECT: Transition ERB Meeting Report

DS&T/FBIS/ESG/ADD/SES:LSteinberg:mlh/733-5936 (14SEP87)

Distribution:

Original - C/ESG

1 - C/HED

1 - C/FED

1 - C/PROD

1 - C/ADD

ADD Staff

1 - C/OPS

1 - SAM/PROD

1 - SA/OPS

1 - W. Pratt, COTR

1 - LEC, Plainfield

1 - LEC, Reston

1 - GE/SES Staff

1 - GE/SES Chrono

ATTACHMENT A

T-ERB Attendees

M. Tanigawa
J. Berthiaume
S. Kaback
J. Wisor
L. Steinberg
D. Ohara
J. Shipley
J. McGowan
B. Pratt

J. Racz

STAT

ATTACHMENT B

TRANSITION ERB

AGENDA

1)	Critical Reports	No. to Review
	Discrepancy Reports	2
	HU-DR-E-066-87	
	HU-DR-E-070-87	
2)	Discrepancy Reports	
	New DRs	3
	CO-DR-E-042-87	
	CO-DR-E-043-87	
	CO-DR-E-044-87	
	DRs in process	6
	HU-DR-E-018-87	
	HU-DR-E-030-87	
	HU-DR-E-042-87	
	HU-DR-E-043-87	
	HU DR-E-051-87	
	HU-DR-E-064-87	
3)	Action Items	9
4)	Open Discussion	

ATTACHMENT C

FBA DISCREPANCY REORT STATUS

15 September 1987

DR #	SUBMISSION DATE	PROBLEM IDENTIFICATION		
CO-DR -E-042	09-08-1987	WSS Queues Stalling/Stopping		
ERB ACTION				
ACTIONEE	STATUS	PRIORITY	DATE DUE	DATE CLOSED
LEC	Complete	B		09-10-1987
DESCRIPTION				
WSS queues frequently stalled on wire items being transmitted.				
ERB COMMENTS				
Completed with the release of Xyplex.				

DR #	SUBMISSION DATE	PROBLEM IDENTIFICATION		
CO-DR -E-043	09-08-1987	XYPLEX Configuration/Device Files Incorrect		
ERB ACTION				
ACTIONEE	STATUS	PRIORITY	DATE DUE	DATE CLOSED
LEC	Complete	B		09-14-1987
DESCRIPTION				
Port and device parameters incorrect on delivered software.				
ERB COMMENTS				
The ERB approved, LEC is directed to implement the change.				

DR #	SUBMISSION DATE	PROBLEM IDENTIFICATION		
CO-DR -E-044	09-08-1987	PWSSGATE Crashes On Message With No Bells Count		
ERB ACTION				
ACTIONEE	STATUS	PRIORITY	DATE DUE	DATE CLOSED
LEC, E Brewer	Complete	B		09-14-1987
DESCRIPTION				
PWSSGATE process crashed with a message with 1BELLS only. (See example)				
ERB COMMENTS				
Ed established a default of 0,for work around. Problem is resolved.				

DR #	SUBMISSION DATE	PROBLEM IDENTIFICATION		
HU-DR -E-070	09-08-1987	Terminal Lockup On RIM3 After Selective Directory Menu Store		
ERB ACTION				
ACTIONEE	STATUS	PRIORITY	DATE DUE	DATE CLOSED

FBA DISCRENPANCY REPORT STATUS

PAGE: 2

Closed

A

09-17-1987

DESCRIPTION

While operating as RIM3, user was unable to proceed after attempting to store Selective Directory Menu called on LOOK1. User logged off and logged on to return to normal.

ERB COMMENTS

The problem can't be re-created. Recommended to be kept as documentation if re-occurs.

DR #

HU-DR -E-066

SUBMISSION DATE

09-09-1987

PROBLEM IDENTIFICATION

Visual Arts For WSS Working
Sporadically

ERB ACTION**ACTIONEE**

LEC

STATUS

T/I

PRIORITY

A

DATE DUE

09-17-1987

DATE CLOSED**DESCRIPTION**

Visual alert for immediate incoming items works sporadically. Four immediates received in timeframe (1400-1500 GMT), but only one visual alert noted. Visual alert "immediate message incoming" should flash for all incoming immediates.

ERB COMMENTS

Investigation of the log is required to determine frequency of problem.

DR #

HU-DR -E-068

SUBMISSION DATE

09-10-1987

PROBLEM IDENTIFICATION

Xyvision Composition Error

ERB ACTION**ACTIONEE**

ADD

STATUS

T/I

PRIORITY

B

DATE DUE

09-17-1987

DATE CLOSED**DESCRIPTION**

A rule of Daily Report composition states that a column or page break should not occur after a subslug; rather, two lines of text are required; both XYV compositors and LECs, Cunliffe tell me that they can't resolve the issue (i.e. neither manual (cont'))

ERB COMMENTS

Mal and Alison to investigate.